


## Calibrating the board

If the pen and pointer/cursor on the board are not aligned correctly then the board needs to be calibrated.

The calibration program can be accessed from the Promethean icon on the task bar or from the Studio dashboard.

### Calibrating from the taskbar

- Right click over the Promethean driver icon on the task bar (this may be simpler with the mouse than the pen unless the calibration is only slightly out).
- Select the “Calibrate” option.
- Follow the on screen instructions, using the pen to touch the centre of the crosses as accurately as possible.



### Calibrating from the dashboard

- Select the “Configure” tab.
- Select the “Calibrate Board” option.
- Follow the on screen instructions, using the pen to touch the centre of the crosses as accurately as possible.

